

Healthy Care™ High Chair Rework Notification

A voluntary Rework has been announced for some of these products.

Mattel India is voluntarily asking consumers to contact it and have their Healthy Care™ High Chairs reworked. These high chairs have a frame that folds flat for storage and a three position reclining seat. The model number of the high chair is located on the back of the seat.

Healthy Care™ High Chairs contain tray storage pegs on the rear legs that children can fall on or against posing a laceration hazard. No incidents have been reported from India.

Only Healthy Care™ High Chairs with tray storage pegs on the rear legs are included in this notification. No other high chairs are affected.

Only Healthy Care High Chairs manufactured before December 2006 are included in the rework. If the fourth digit in the date code is 6 or less, the Healthy Care High Chair is included in the rework.

B2875 Healthy Care™ High Chair



B8866 Healthy Care™ High Chair




Use this online guide to determine if the high chair you own is affected by this notification.

Please have your high chair near you as you continue.

Locate your high chair's product number. The product number is located on a white sticker on the back of the seat. Please use the below image to assist you in locating the product number.

Healthy Care™ High Chair



If your Healthy Care™ High Chairs is not product number **B2875** or **B8866**, you are **not affected** by this notification and you can continue to use your high chair.

If your is Healthy Care™ High Chair is product number **B2875** or **B8866** or if you do not know the product number of your high chair, Please turn your Healthy Care™ High Chair around to view the back of the product.

Sample Image of Products (Colors, fashion, and toy accessories vary)



Does your Healthy Care™ High Chair have the tray storage pegs as illustrated in the above sample images?

1) If your High Chair does not have tray storage pegs as illustrated in the above image, you are **not affected** by this notification and can continue to use your High Chair

2) If your Healthy Care™ High Chair has tray storage pegs that match the above image you **are affected** by this notification.

Please discontinue using your Healthy Care™ High Chair immediately.

If your product is affected by the notification and you wish to receive the free rework kit or if you have any questions in relation to this notification, please contact Mattel by email at service.india@mattel.com or by phone at 1-800-2090102.

Our greatest concern has always rested with the safety of the children who play with our toys, which is why we have responded promptly in an effort to maintain the trust of the families that have allowed us to be part of their lives.